

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED**

**Nº 4139**

**DATE INSPECTED** 7/15/40

**IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM**

192

**HOUSE NO.** 878

**DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH**

192

3'6" d

**SIZE OF PIPE USED** 6"

**WAS LATERAL AT CURB?**

**NAME OF CONTRACTOR**

Tony Palone


**WAS ATTACHED TO MAIN**

**SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.**

Lot #9610  
Hse #878

SENACA AVE N.E.

N



**SIGNED**

John Chamer  
**INSPECTOR FOR CITY**

**FILED AT ENGINEER'S OFFICE**

7/15/40

**REMARKS.**

LATERAL BROKE 2' OUT FROM CURB. WAS FULL OF DIRT

HAD TO RELAY 13' FROM MAIN TO CURB. Laterals not connect to  
of main ~~was~~ about 2' gap. Lines didn't line up either

Replacing sewer line  
in yard as per  
3/31

NOT TO BE ANSWERED BY INSPECTOR  
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
NO. 4139  
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/15 1915

RECEIVED OF Tom Palmer FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Her. Ackerman

TO TAP Sanitary SEWER, ON THE West

OF Acacia AVE., TYPE OF STREET Dist.  
ST.,

THE PREMISES BEING LOT No. 9610 HOUSE No. 878

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Tom Palmer

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.