

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4148

DATE INSPECTED 8-9-40

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

134° From MH 50 of Medill at Wk
Edge of Walk and 139° From
dead end to MH at west edge of

HOUSE NO. 1309

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? YES.


NAME OF CONTRACTOR

Del. Earley

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED

Tar Joints used
12" pipe laid before
M.H. was there. Told me
to be on job at
10:00 am. was on
job at 10:15



SIGNED

Shaw

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

8/14/40

REMARKS:

For Further data on this lateral see N.R. 148
50

148
50

OK
GL

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

No. 4148

MASSILLON, OHIO, 8-9 1919

RECEIVED OF Delbert Bordner FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Delbert Earley

TO TAP Sanitary SEWER ON THE West

OF 11th St. NE. AVE., TYPE OF STREET Asphalt
ST.,

THE PREMISES BEING LOT No. 7452 HOUSE No. 1309

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR D. Earley

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

*New acct. Rate \$2.00
Entered Ledger Jan. 1. 1941*

10-7