

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4150

DATE INSPECTED 8/22/40

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 110'

HOUSE NO. 518

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 110' - 11' d

SIZE OF PIPE USED 4"


WAS LATERAL AT CURB?

NAME OF CONTRACTOR Smart

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

ALLEY, N. OF NE LEAVE S.W.



SIGNED

John E. Humer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS. LOWERED Y- 8 1/2" AT MAIN. RELAID LATERAL.

8/24/30

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4150
PERMIT TO TAP SEWER

(G. Reigenbaum)
Owner

MASSILLON, OHIO, 120 19

RECEIVED OF

FEE OF \$2

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT No.

HOUSE No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

In ledger 10800
Relaying lateral