

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

4-15

Nº. 4166

DATE INSPECTED 9-4-40

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

171° From MH. South 6° Deep etc

HOUSE NO. 614

DISTANCE FROM FIRST MANHOLE

SIZE OF PIPE USED 6"

**DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

Internal #16 sewer Rec

WAS LATERAL AT CURB? Yes

NAME OF CONTRACTOR

Tony Balano

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

The former owners of this prop. ordered the lat
on the no. side of lot. this made contrator to use
1/8 Bend at curb making a
crook in lateral inside of
curb line

Kalk tite and gule joints
used.

SIGNED


Doc Shorter
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10/4/40

REMARKS:

Lat. at curb is 38' W. of S. prop. line and 225° S. of N. prop. line. 25° N. of S. side of H. at curb line



800
10/1/40
Sedgew
New account.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
NO. 4166
PERMIT TO TAP SEWER

MASSILLON, OHIO, 1940
RECEIVED OF Frank Louis Palmer Co. FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Frank Louis Palmer Co.

TO TAP Sanitary SEWER ON THE East

OF Gay St. AVE., TYPE OF STREET Dist.
ST.,

THE PREMISES BEING LOT No. 2867 House No. 214

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Frank Louis Palmer Co.

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.