

7
25

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4169

DATE INSPECTED 10-16-40

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM** _____

HOUSE NO. 2402

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH** _____

SIZE OF PIPE USED 4"

159' From M.H. East 6th Dec


WAS LATERAL AT CURB? under walk

NAME OF CONTRACTOR _____

Smart

WAS ATTACHED TO MAIN _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10/17/40

REMARKS:

Lateral walk 159' E. of East side of House

#801
New acct.
Entered - Ledger Jan 1, 1941

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4169
PERMIT TO TAP SEWER

DATE INSPECTED _____
FIRST RAYHOLE DOWN SYSTEM _____
MASSILLON, OHIO, 10-7-1941

RECEIVED OF Jacob Rippke FEE OF \$ _____

FOR WHICH PERMISSION IS GRANTED L. Smart

TO TAP Sanitary SEWER, ON THE North

OF Lincoln Way NW AVE., TYPE OF STREET Eric
ST.,

THE PREMISES BEING LOT No. 10179, HOUSE No. 2402

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L. Smart

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.