

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4176

41
11/18

DATE INSPECTED 10-28-40

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

HOUSE NO. 475

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM-TO DITCH AT
CURB LINE AND DEPTH**

SIZE OF PIPE USED 6"

100' From 17th. No. 41 From Mt. 50
5.5 Deep


WAS LATERAL AT CURB? Yes.

NAME OF CONTRACTOR

Smart

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Doc
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

19th St N.W.

10/31/41

Sedgew. Nov. 15. 1940
New account.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4176
PERMIT TO TAP SEWER

MASSILLON, OHIO, 1940
RECEIVED OF Edgewood FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED 1st St.
TO TAP 1st St. SEWER ON THE 1st St.
OF 1st St. AVE., TYPE OF STREET 1st St.
ST.,
THE PREMISES BEING LOT No. 5298 HOUSE No. 475
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR Edgewood

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.