

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4187

DATE INSPECTED 2-8-41

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

East

HOUSE NO. Rear of 540

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

117' W
179' E of M.H. 4' Deep at Mail

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? No


NAME OF CONTRACTOR

Delbert Early

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 7' Long
Saddle Connection made to main



SIGNED Julius Wilson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: New house. Rear of lot, House #540 Pennock Ave. S.W.

8:30

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

No. 4187

MASSILLON, OHIO, 2/7

RECEIVED OF

FEE OF \$ 2.50

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET

ST.,

THE PREMISES BEING LOT No.

HOUSE No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.