

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4204

DATE INSPECTED 3-31-41

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

218' Center of Street

HOUSE NO. 221

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? yes.

NAME OF CONTRACTOR Delbert Entley

WAS ATTACHED TO MAIN No.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 7' Deep at connection E.
Lateral 7' Deep at house
Lateral 36' Long From house
to curb



sewer

Willow N.E.

SIGNED Julius Solon
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

OK

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4204
PERMIT TO TAP SEWER

DATE WHEN THIS PERMIT IS TO BE ANSWERED BY INSPECTOR
MAINTAIN LOCATION FROM
MAINTAIN LOCATION FROM

MASSILLON, OHIO,

3/31

19

RECEIVED OF

E. Early

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED

Map Sprinkle

TO TAP

San

SEWER, ON THE

South

OF

Allen NE

AVE., TYPE OF STREET

driv

ST.,

THE PREMISES BEING LOT No.

7774

HOUSE No.

221

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Robert Early

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.

*New account
Entered in ledger 7/1/41
\$8.00*