

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4216

DATE INSPECTED 5-10-41

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 90' side walk

HOUSE NO. 2761

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH


WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN outside sidewalk

NAME OF CONTRACTOR Smart

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 6' Deep at outside of walk.
Lateral 4' Deep at corner of house
Lateral 25' Long corner house to walk



Sidewalk
Sewer

Lincoln way W.

SIGNED Julius Johnson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 5-15-41

REMARKS: Sewer under sidewalk; + mark on top of sidewalk
connection outside of sidewalk 10' off curb

NOT TO BE ANSWERED BY INSPECTOR

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NO. 4216

PERMIT TO TAP SEWER

New account
ledger 7/10/41
800

DATE ISSUED 7/26

MASSILLON, OHIO

15

RECEIVED OF

FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET
ST.

THE PREMISES BEING LOT No.

HOUSE No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.