

8
31

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 4228

DATE INSPECTED 6-2-41

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

227' connection to main in
239' out in street to curb Notes

HOUSE NO. New house

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? No

NAME OF CONTRACTOR

Smart

WAS ATTACHED TO MAIN yes with wye

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 10' Deep at main
Lateral 6' Deep at curb
Lateral 6' 5" Deep at house
Lateral 94' Long house to main
Lateral 76' Long house to curb

curb

curb

M.H.

227'

12'

Lindbergh Ave N.E.

SIGNED


Julius Holson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

6-3-41

REMARKS: Connection was to main with wye.

Note: started to dig in wrong place and
then redig the ditch went straight to the
reason, took distance from M.H. to M.
lateral distance instead of lateral mea
Smart to blame - Leo Wallace



NO. 4228

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/21 1919

RECEIVED OF

Jess Beckleiter

FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED

L. Smart

TO TAP

Sanitary

SEWER, ON THE

North

OF

1860 Lindbergh Ave

AVE.,
ST.,

TYPE OF STREET

Gravel

THE PREMISES BEING LOT No.

9123

HOUSE No.

1860

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

L. Smart

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.

New account.
Lidger 8/16/41
\$8.00