FOLLOWING DATA TO BE ANSWERED BY INSPECTOR - 4235 AND SIGNED WHEN RETURNED DATE INSPECTED IF SO HOW AND LOCATION FROM QU'OUT I'M STE SIZE OF PIPE USED WAS LATERAL AT CURBY THIS /ine Relaid NAME OF CONTRACTOR SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED Laterals. 5' Deep at curb Lateral 6 Deep at house Lateral 39,5 Longhouse tocorb MOTOLATHOO ROTALON FILED AT ENGINEER'S OFFICE REMARKS. This line was relaid Due to lateral Tromble. and was from the curb up to the house

21		OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER
15	W,	A CONTRACTOR OF THE STATE OF TH
Op.	13 .	RECEIVED OF THE OF \$2
	1 14 11	FOR WHICH PERMISSION IS GRANTED DATE.
	1 p %	TO TAP SEWER, ON THE
	8.11	OF AVE., TYPE OF STREET ST., THE PREMISES BEING LOT NO.
	Of Eg	Work to be done in accordance with Ordinance No. 2323, duly passed by the City Counci Rules of the Department of Public Service.
	10	Name of Contractor 1. Value 2.
		Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.
. 5.17 5.74	(1986) 医网络肾髓 化电影 医乳腺 经产品 化二氯化	3、4、4、4、4、4、4、4、4、4、4、4、4、4、4、4、4、4、4、4