

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No. 4240

DATE INSPECTED 6-24-41

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

166' out in street

HOUSE No. 578

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

SIZE OF PIPE USED 4"

WAS LATERAL AT CURB? Reopened


NAME OF CONTRACTOR

Earley

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 10' Deep at main
Lateral 3' Deep at curb



SIGNED Julius Smolson

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

OK G.W. 6-30.

REMARKS:

this lateral causing trouble; was opened up (2) times. broken pipe
just off main line was found. Pipe were replaced by Earley contractor

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 4240

PERMIT TO TAP SEWER

MASSILLON, OHIO,

6-20

19

RECEIVED OF

Hanna Myers

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

Mr. F. J. Myers

TO TAP

Low

SEWER, ON THE

E.

OF

Encl. A. E.

AVE.,

TYPE OF STREET

ST.,

dirt

THE PREMISES BEING LOT No.

725

HOUSE No.

512

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE

NAME OF CONTRACTOR

Mr. Delbert Early

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

Already in ledger C 800
No Change in Rate
Repairing Sewer Line.