

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No. 4265

DATE INSPECTED 8-20-41

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

6.5' out in street

HOUSE No. 927

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

SIZE OF PIPE USED

6"

WAS LATERAL AT CURB?

No
yes

NAME OF CONTRACTOR


Palone

WAS ATTACHED TO MAIN

Hub saddle

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 9' Deep at main line
Lateral 6' Deep at property line
Lateral 6' Deep at house
Lateral



No curb; no curb line.

SEWER

15th St. S.W.

SIGNED

Julius Holman
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

OKGCW Aug 22

REMARKS:

Cellar dug no house on lot; this measurement is up street

Lateral 33.5' Long house to property line
Lateral 33.5' Long house to main

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NO. 4265

PERMIT TO TAP SEWER

DATE INSTALLED
FIRST MANHOLE DOWN STREAM

MASSILLON, OHIO,

7/19

19

RECEIVED OF

Donald Harrison

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Long Calver

TO TAP

Sanitary

SEWER, ON THE

West

OF

15th St.

AVE., TYPE OF STREET
ST.,

West

THE PREMISES BEING LOT No.

8226-77

HOUSE No.

927

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Long Calver

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.