

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4269

DATE INSPECTED 8-27-41

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

76' out in street

HOUSE NO. 1022 new house

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? 6' Back of curb


NAME OF CONTRACTOR

Palone

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 5' Deep at curb
Lateral 6' 5" Deep at house
Lateral 32' Long house to curb



SIGNED Julius Tolson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE OK G.C.W. - Aug 29

REMARKS:

Soil "Red clay" + mark on top of curb

(over)

Failure was found on back of old
(3) three joints taken up to line up with
ditch at curb. $\frac{1}{8}$ Bend used at curb

New account

Settled Jan. 1, 1942

800-19

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4269
PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/21 1942

RECEIVED OF Irving Polone FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Richard Williams

TO TAP Albion Street SEWER, ON THE South 7/20 7784-83 AVE., TYPE OF STREET dirt

OF South 7/20 7784-83 ST.,

THE PREMISES BEING LOT No. 576-82, HOUSE No. 1022-2nd

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Irving Polone

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.