

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4278

DATE INSPECTED 9-19-41

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

94' out in street

HOUSE NO. _____

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH** _____

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? Yes. No curb in curb line


NAME OF CONTRACTOR Smart

WAS ATTACHED TO MAIN _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 7' Deep at curb line
Lateral 6.5' Deep at house
Lateral 52' Long house to curb line

No curb curb line
← Sewer
15th St S.E.



SIGNED

Julius Hansen
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10-3-41 GCU

REMARKS:

Note 4' & 6' measurements are from corner of porch
Soil. Clay top sand & gravel bottom.

4/16
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
NO. 4278
PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/16

RECEIVED OF

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

15th St. S.E. AVE., TYPE OF STREET dirt

THE PREMISES BEING LOT No.

5205 HOUSE No. 7416

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

Ledger 10/1/41
Rate 8.00