

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4282

DATE INSPECTED 9-18-41

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

26' in side walk.

HOUSE NO. 2224

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? yes

NAME OF CONTRACTOR Tony Dalone N

WAS ATTACHED TO MAIN _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 9' Deep at side walk
Lateral 9' Deep at house
Lateral 63.5' Long house to side walk



side walk sewer walk 26' 26'

Lincoln Way W.

SIGNED Julius Troson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 10-3-41 GCU

REMARKS: Sewer under side walk + mark on top of side walk
Soil. Hard Clay sewer laid before wall was up.

1/6.0 sewer laid from side walk
to basement. "Bage" not under whole house

7/23

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4282
PERMIT TO TAP SEWER

DATE WHEN THIS PERMIT WAS ISSUED

MASSILLON, OHIO, Sept. 18 1915

RECEIVED OF Ira A. Adams

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Tony Palone

TO TAP Sanitary SEWER ON THE North

OF Lincoln Way NW AVE., TYPE OF STREET resid
ST.

THE PREMISES BEING LOT No. pt of 168 HOUSE No. 2224

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Tony Palone

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.