

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 4286

DATE INSPECTED 9-29-41

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

124' out in street

HOUSE No. 1127

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? yes.


NAME OF CONTRACTOR

Palone

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral/ 5' Deep at curb
Lateral/ 7' Deep at house
Lateral/ 26' long house to curb



curb
sewer

Tremont Ave S.E.

SIGNED

Julius Holson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10-3-41

GCU

REMARKS:

+ mark on top of curb. Soil: clay

(over)

5/13
OFFICE ADDRESS FROM FALL 1891

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
NO. 4286
PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/26 1915
RECEIVED OF Daniel Marchant FEE OF \$ 2.
FOR WHICH PERMISSION IS GRANTED Daniel Marchant
TO TAP Sanitary SEWER ON THE South
OF Trent Ave AVE., TYPE OF STREET Dist
ST.,
THE PREMISES BEING LOT No. 3447 HOUSE No. 1127

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Delbert Canby

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.