

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

N^o 4287

AND SIGNED WHEN RETURNED

DATE INSPECTED 9-30-41

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

31' out in street

HOUSE NO. 1430

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? yes.

NAME OF CONTRACTOR

Smart


WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 6.5' Deep at curb

Lateral 9' Deep at house

Lateral 79' Long house to curb



SIGNED Julius Ineson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE ON Oct 8 1941

REMARKS:

lateral found under lamp post Soil. Hard clay

5/53

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NO. 4287

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/29 1915

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER. ON THE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT No.

HOUSE No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.