

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4292

DATE INSPECTED 10-21-41

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

Connection was made to st.
in Mt. as shown

HOUSE NO. _____

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH** _____

SIZE OF PIPE USED 10"

WAS LATERAL AT CURB? _____

To Stub

NAME OF CONTRACTOR

B & H Const. Inc.

WAS ATTACHED TO MAIN in Mt.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 7.5' Deep at Mt. out in street


Lateral 10' Deep at Creek Wall

Lateral 38' Long Mt. to Creek Wall

← N.

No curb

4th St S.E.



SIGNED

Julius J. Hansen
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Soil. old fill mixed dirt

OK GCW - 10-23-41

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NO 4292

PERMIT TO TAP SEWER

MASSILLON, OHIO, 1915

RECEIVED OF

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER. ON THE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT No.

House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

No Change in Rate.

Pl. of R.S.