

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4294

DATE INSPECTED 10-16-41

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

175' out in street

HOUSE NO. _____

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH** _____

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? yes.

NAME OF CONTRACTOR Palone

WAS ATTACHED TO MAIN _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 7.5' Deep at curb
Lateral 8' Deep at house
Lateral 99' long house to curb



SIGNED Julius Molson

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

OK GCW Oct 21

REMARKS: mark on top of curb

Soil. Sandy

cover

1st Bldg. was a cement block
shop of Nick Cinda No cellar under
Bldg. to be remodeled for dwelling

6/29

new

✓

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4294
PERMIT TO TAP SEWER

DATE ISSUED 10/13 1913
FIRST WARDEN BOARD STREET
MASSILLON, OHIO, _____
RECEIVED OF H. Malone FEE OF \$2.00
FOR WHICH PERMISSION IS GRANTED to tap
TO TAP San SEWER ON THE E
OF Dunsmuir St. AVE., TYPE OF STREET Driv
ST.,
THE PREMISES BEING LOT No. 3394 HOUSE No. _____
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR H. Malone

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.