

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4306

DATE INSPECTED 1-22-42

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

57.5' out in street

HOUSE NO. 372

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? No.


Yes.

NAME OF CONTRACTOR

Tony Palone

WAS ATTACHED TO MAIN Hub Saddle

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



Lateral 12' Deep at main

Lateral 8' Deep at curb line

Lateral 6' Deep at house

Lateral 37' Long house to curb line

Lateral 30.5' house to main

57.5'
27th St. N.W.

SIGNED

Julius Holson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE OK - Jan 26 1942

REMARKS:

Soil Hard Clay

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NO. 4306

PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/19

RECEIVED OF

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT No.

HOUSE No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.