

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED**

**Nº 4309**

**DATE INSPECTED** 12-31-41

**IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM**

339' north from Green Ave

**HOUSE NO.** 310

**DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH**


**SIZE OF PIPE USED** 4"

**WAS LATERAL AT CURB?** yes.

**NAME OF CONTRACTOR** Palone

**WAS ATTACHED TO MAIN** \_\_\_\_\_

**SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.**



Lateral 7.5' Deep at main line  
Lateral 6.5' Deep at curb  
Lateral 6' Deep at house  
Lateral 46' Long main to house  
Lateral 33.5' Long curb to house

curb

Sewer 11th St. S.W.

**SIGNED** Julius Hansen  
**INSPECTOR FOR CITY**

**FILED AT ENGINEER'S OFFICE** OK-G.C.W 2-2-42

**REMARKS.** Note: lateral was at curb "But" was relaid to get more to  
to Basement Soil Stoney & Hard Clay

COVE

could not locate MH. on Green Ave. S.W.  
measurements taken from City Hall Records  
Green Ave cut b. up side walk North 339'  
Witch was O.K. to later a/

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
No. 4309  
PERMIT TO TAP SEWER

#.  
new  
✓  
2

MASSILLON, OHIO, 1/28 1928

RECEIVED OF Wm. H. Heflin FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED P. Palano

TO TAP San SEWER, ON THE 6

OF 11th St AVE., TYPE OF STREET dist

THE PREMISES BEING LOT No. 3131 HOUSE No. 310

NAME OF CONTRACTOR P. Palano

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.