

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

✓
29

DATE INSPECTED 3-10-42

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

202 out in street

HOUSE NO. 383

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? yes.

NAME OF CONTRACTOR

L.H. Smart

WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 7' Deep at curblin
Lateral 3.5' Deep at Porch
Lateral 33.5' Long Porch to curblin



N. →

"No curb" curblin

SEWER →

25th St N.W.

SIGNED

Julius Johnson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

3-16-42

REMARKS:

Sail clay

"New lateral"

OK
G.F.I.

8 o'clock 3/3/4

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4312
PERMIT TO TAP SEWER

DATE ISSUED 3/2 1914
FIRST MANHOLE DOWN STREAM
MASSILLON, OHIO.
RECEIVED OF Jacob Sander FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED Jacob Sander
TO TAP Sanitary SEWER ON THE West
OF 25th St. N.W. AVE., TYPE OF STREET dist
THE PREMISES BEING LOT No. 8692 HOUSE No. 383

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L.W. Smart

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.