

'New lateral'

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 4318

DATE INSPECTED 4-2-42

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

17' out in street

HOUSE No.

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? yes.

NAME OF CONTRACTOR

P.E. Bickel


WAS ATTACHED TO MAIN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral 6' Deep at curb
Lateral 6' Deep where cont. stopped
Lateral 47' Long curb to where cont. stopped

No
cellar
dug

cont.
stopped



SIGNED

Julius Holson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

4/4/42

REMARKS:

No cellar dug. lateral tied in 27' East of X mark on cu
to dotted line, thence 37' North to where cont. stopped "soil cla

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 4318

PERMIT TO TAP SEWER

DATE WHEN AND LOCATION FROM
MASSILLON BOARD OF HEALTH

MASSILLON, OHIO,

4/1

19

RECEIVED OF

P. F. Rickel

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Willard Road

TO TAP

sanitary

SEWER, ON THE

South

OF

Little and NE

AVE.,
ST.,

TYPE OF STREET

drift

THE PREMISES BEING LOT No.

7640

HOUSE No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

P. F. Rickel

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.