

New Connection
No. 4334

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-24-42 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 24' House line to + on curb


HOUSE NO. 887 DISTANCE FROM FIRST MANHOLE

SIZE OF PIPE USED 4" ~~DOWN~~ STREAM TO DITCH AT CURB LINE AND DEPTH 14'6" upstream, 7'6" Depth

WAS LATERAL AT CURB? Yes. NAME OF CONTRACTOR Molson

WAS ATTACHED TO MAIN _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



14'6" Lateral to manhole upstream
24' House line to + on curb,
7'6" Lateral depth at curb,
+ on curb,
56' Lateral curb to house,
2'4" Lateral to house corner.
Soil Clay
House facing east,
3'6" Depth Lateral at house.

SIGNED H. Herrick INSPECTOR FOR CITY FILED AT ENGINEER'S OFFICE OK GCW June 25

REMARKS: Lateral runs into manhole south.
Water line in part of ditch

New Connection.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 4334

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/1 1918

RECEIVED OF

Home Descriptive Bureau

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Home Descriptive Bureau

TO TAP

Sanitary

SEWER, ON THE

West

OF

Pamphill Circle N.E.

AVE.,
ST.,

TYPE OF STREET

Circle

THE PREMISES BEING LOT No.

7790

HOUSE No.

887

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Julius Malcom

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.