

Old connection,

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

Nº 4343

AND SIGNED WHEN RETURNED

7-15

DATE INSPECTED

6-25-42

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

10' House line to connection at main

HOUSE NO.

218

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

263'6" Lateral to Manhole. 6'3" Depth to.

SIZE OF PIPE USED

4"

WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN


Yes.

NAME OF CONTRACTOR

Paloni

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Striped dirt.



SIGNED

W. H. Hirsch

INSPECTOR FOR CITY

Hub saddle.
Rear Building facing north. @EW 6-26
FILED AT ENGINEER'S OFFICE

REMARKS:

This lateral is for the rear service to main line.
only a cellar drain.

Old Connection,

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 4343

PERMIT TO TAP SEWER

MASSILLON, OHIO, June 25 1918

RECEIVED OF Long Palmer

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Rose Anthony

TO TAP Sanitation

SEWER ON THE West

OF Market Street Alley ST.,

TYPE OF STREET Alley

THE PREMISES BEING LOT No. 97

HOUSE No. 218

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Long Palmer

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.