

New Connection

No. 4346

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

✓

DATE INSPECTED 7-8-42

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

61' Building line to lateral

HOUSE NO. No number

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

13' 8" Depth at main line connection

SIZE OF PIPE USED 6"

149' Lateral to down stream M. Hole.


WAS LATERAL AT CURB? Yes

NAME OF CONTRACTOR

Bickel

WAS ATTACHED TO MAIN Yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



6" Tile

6" Hub saddle

6" 45

149' Lateral to down stream Manhole.

61' Building line to lateral.

39' Lateral connection to building.

13' 8" Lateral depth at main line

3' Depth lateral at Building

Soil sand

Building facing north

SIGNED H. Henrich
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE OK GCW July 13

REMARKS:

New connection

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 4346

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/3 1926

RECEIVED OF P. E. Beichel

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Tap on Rotten Bearing

TO TAP Sanitary

SEWER, ON THE South

OF Pennock St.

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT No. no lot #

House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR P. E. Beichel

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.