

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 4354

DATE INSPECTED

9/8/42

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

114

HOUSE NO.

1712

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

6"

144' - 9' deep.

WAS LATERAL AT CURB?

yes


WAS ATTACHED TO MAIN

yes

NAME OF CONTRACTOR

Molson

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

John Ehmer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

GCW

Sept 10 42

REMARKS:

Clay soil.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 4354

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/7

RECEIVED OF James Deasdale

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Same

TO TAP San

SEWER ON THE 77

OF Jefferson

AVE., TYPE OF STREET Parcel
ST.,

THE PREMISES BEING LOT No. 8084

HOUSE No. 1712

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR J. Malson

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.