

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED**

**Nº 4372**

DATE INSPECTED 10/9/42 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 7  
 HOUSE No. 233 UP  
 SIZE OF PIPE USED 4" UP DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 7' 5'd.  
 WAS LATERAL AT CURB? No. NAME OF CONTRACTOR Smart  
 WAS ATTACHED TO MAIN Yes  
 SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

EDWIN. AVE. S.E.




Relay job.

7'  
UP Stream.

SIGNED John Thayer  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE GCW - 10-21-42

REMARKS: 2 lines on one y. 4' off main disconnected this  
and fixed the other one the best it could be.



OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NO. 4372

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/7

RECEIVED OF

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE.,  
ST.,

TYPE OF STREET

THE PREMISES BEING LOT No.

HOUSE No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.