

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4375

13-37

DATE INSPECTED _____ IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____


HOUSE NO. 228

SIZE OF PIPE USED 6" up DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 73 ft. up stream

WAS LATERAL AT CURB? Yes NAME OF CONTRACTOR Bickel

WAS ATTACHED TO MAIN _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____ INSPECTOR FOR CITY FILED AT ENGINEER'S OFFICE GCW - Nov 10-

REMARKS: Actual inspection done by Chas. Urban inspector on main line in Orange St. clay soil

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
NO. 4375
PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/17
RECEIVED OF L. H. Bickel FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED
TO TAP San SEWER, ON THE
OF Orange AVE., TYPE OF STREET driv
THE PREMISES BEING LOT No. 2282 HOUSE No. 228

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Bickel

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.