

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 4396

3

DATE INSPECTED 4/10/43

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

109

HOUSE NO. New house

DISTANCE FROM FIRST MANHOLE
DOWN-STREAM TO DITCH AT
CURB LINE AND DEPTH

109'

8' deep

WAS LATERAL AT CURB? yes

NAME OF CONTRACTOR

Smart.

WAS ATTACHED TO MAIN yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

9TH ST. N.E.

N

12

7'd

11

10

9

8

7

6

5

4

3

2

1

8'd

109'

SIGNED

John Chover

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

4-13-43

REMARKS:

Clay soil.

CEP

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 4396

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/7 1915RECEIVED OF L.H. SmithFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED L.H. Smith ByronTO TAP SEWER ON THE

SEWER, ON THE

OF 7th St.

AVE.,

TYPE OF STREET oiled

ST.,

A

THE PREMISES BEING LOT NO. 4336 (1)HOUSE NO. New442

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L.H. Smith

Note. This permit covers work outside of building only. Any work inside
 of building is subject to Massillon Board of Health Regulations.