

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

3
3

Nº 4397

DATE INSPECTED 4/22/43

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM** 160

HOUSE NO. New house no number

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

SIZE OF PIPE USED 4"

160 - 8 d


WAS LATERAL AT CURB? yes

NAME OF CONTRACTOR Smart

WAS ATTACHED TO MAIN yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

9th ST. N.E.



curb line

160

SIGNED

John E. Houser

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

M.H.

REMARKS:

sand soil.

OK CD

4-23-43

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 4397

PERMIT TO TAP SEWER

RECEIVED OF

MASSILLON, OHIO

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT No.

House No.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.