N_{\cdot}^o 4399 and signed when returned

7/ser	DATE INSPECTED 4/15/43	IF SO HOW AND LOCATION FROM 407
	House No. /237	DISTANCE FROM FIRST MANHOLE
	SIZE OF PIPE USED 67	CURB LINE AND DEPTH
	WAS LATERAL AT CURBY Vec	
	WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR Small
a(c		LATERAL TO WALL OF BUILDING SERVED.
	Lincoln. Wa	
	and december of the control of the c	.12 /0
		Pote mod programmer / 5 6 d
4), Jion	, 2323, oper essails er mit Turk Chai	or subsamina with the account of account with commands to
		The administration of the state
	<u> </u>	401 > 115
	1. 1 Ost	met of the second of the secon
yni. Taw ob	SIGNED INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE
	REMARKS. C/a v 5011	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE M^o 4399 PERMIT TO TAP SEWER

	그 가지 않는 그는 그는 그는 이 가지를 하는데 그 지수는 그는 그를 다양하는데 그는 사람들은 微微했다.
1	ender Bestades Erden in in in in in in de boerde experience experience de la company d
-	MASSILLON, OHIO, 15
1	To de la constant de
, ,	RECEIVED OF FEE OF S
	ing language in the control of the second of the control of the co
	FOR WHICH PERMISSION IS GRANTED TO THE TOTAL OF THE TOTAL
:	FOR WHICH PERMISSION IS GRANTED
	A STATE OF THE STA
÷	TO TAP SEWER, ON THE
	and the first of the second of
	OF AVE., TYPE OF STREET
	// St.,
٠.,	
٠.	THE PREMISES BEING LOT No
ea.	
è	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.