

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No. 4408

DATE INSPECTED 6/15/48

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

118

House No. New House.

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH**

118' 6'd

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? yes

NAME OF CONTRACTOR

Smart


WAS ATTACHED TO MAIN yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Main Ave W.

N
↓

MANHOLE



SIGNED

John Thuermer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Clay soil 2ND lot W of old house.

016

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 4408

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/9 1918

RECEIVED OF L. H. Ernst

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Byron Burch

TO TAP San

SEWER, ON THE S.

OF Main Ave W

AVE.,

TYPE OF STREET Hard Lury

St.,

THE PREMISES BEING LOT No. Rt. D. L. 360

HOUSE No. 2115

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L. H. Ernst

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

2008 = 25th Nov 145c