

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4412

9
19

DATE INSPECTED 6/20/43

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM** 22'

HOUSE NO. Tycon Bearing Corp.

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH** 22' 7'-8" deep.

SIZE OF PIPE USED 4"

WAS LATERAL AT CURB? yes

NAME OF CONTRACTOR Andy Lamonica

WAS ATTACHED TO MAIN yes

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

3 RD. ST, N.W.

**OFFICE,
BLDG.**

N →

Fence

M.H.

22'


SIGNED John E. [Signature]

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

see N.B.
162-P 58



OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4412
PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/31 1921
RECEIVED OF A. J. Lammiman FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED Tyson & Ralston Basin
TO TAP San. SEWER ON THE W.
OF 3rd St. AVE., TYPE OF STREET dirt
THE PREMISES BEING LOT No. 126 HOUSE No. 635

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. J. Lammiman

Note. This permit covers work outside of building only. Any work inside
of building is subject to Massillon Board of Health Regulations.