

Nº 4435

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10/1/43

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

204

HOUSE NO. 1014. New House.

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

204 76" deep

WAS LATERAL AT CURB? yes



WAS ATTACHED TO MAIN yes.

NAME OF CONTRACTOR

Lamonica

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

IRVINGTON. Ave N E.



SIGNED John Chamer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 10-22-43

REMARKS: Found 4" lateral.

OK/H.

Nº 4435

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/1

RECEIVED OF

A. J. Lammica

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED

W. W. Plashett

TO TAP

sanitary

SEWER, ON THE

north

OF

Livingston NE

AVE.,
ST.,

TYPE OF STREET

hard surf

THE PREMISES BEING LOT NO.

6871

HOUSE NO.

1014

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

A. J. Lammica

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.