

10
56

Nº 4445

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11/5/43

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

197

HOUSE NO. 2127

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

197

SIZE OF PIPE USED 6


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Courtland Ave.



SIGNED

John Elmer
M.A.
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 4445

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/2RECEIVED OF A. J. DeanaFEE OF \$ 2FOR WHICH PERMISSION IS GRANTED Michael MullaTO TAP San

SEWER, ON THE

OF Courtland St.AVE.,
ST.,TYPE OF STREET St.THE PREMISES BEING LOT NO. 6023HOUSE NO. 2127

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. J. Deana

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.