FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 4452 AND SIGNED WHEN RETURNED IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT SIZE OF PIPE USED CURB LINE AND DEPTH WAS LATERAL AT CURB?____ NAME OF CONTRACTOR SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. Monroe Ave N.W.

OK

office of the director of public service Nº 4452 PERMIT TO TAP SEWER

FOR WHICH PERMISSION IS	The state of the s	FEE OF SCI LANDED
	The state of the s	TO PA RESULTA LASSTAL SAV
in i lag duyaya ayet		R, ON THE
or		PE OF STREET
THE PREMISES BEING LOT	1111	, House No. 418

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.