

Nº 4456

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 2/24/44

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

207

HOUSE NO.

946. New house

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

207

7 deep

WAS LATERAL AT CURB?

yes

WAS ATTACHED TO MAIN

yes


NAME OF CONTRACTOR

Geo. Earley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Johnson, St. S.E.

N



SIGNED

John Elmer  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Not inspected by me Earley responsible.

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N<sup>o</sup> 4456

## PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/20RECEIVED OF Dr. R. J. BallingerFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED Dr. R. J. BallingerTO TAP SanitarySEWER, ON THE EastOF Johnson St.AVE.,  
ST.,TYPE OF STREET dirtTHE PREMISES BEING LOT NO. Pt. OL 149HOUSE NO. 946WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.NAME OF CONTRACTOR Her. Early

Note. This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.