Nº 4477	LLOWING DATA TO BE ANSWERED BY INSPECTO AND SIGNED WHEN RETURNED
DATE INSPECTED $\frac{5/27/3}{2}$	FIRST MANHOLE DOWN STREAM
HOUSE NO. 337	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 225 - グイe
WAS LATERAL AT CURB?	NAME OF CONTRACTOR Smant
	OF LATERAL TO WALL OF BUILDING SERVED.
CV Septim	
	THE STREET OF TH
	9, e, 7'dee///

SIGNED States FILED AT ENGINEER'S OFFICE

REMARKS:

Of Z

Nº 4477

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	geri veraboa sin redik			1972 ·
	garigisa, hayga bilay selebil	MASSILLO	и, Оніо,	10-7-
. 이 마다를 보다면서 놀래요.				
41 4 4 <u>- 12 13 13 13 1</u> 3	1. 1. 2	may 1 1		FEE OF \$
RECEIVED OF	on the state of th	AROD - 1	e, Inches e contra	FEE OF 35
	\mathcal{A}	M - L I -	4.7	
FOR WHICH PERMISSI	ON IS GRANTED	A. Ale	Le for for	
	K di ma I		1114	tata est de la la la comunidad de la
TO TAP		SEWER, ON THE	177	
ika da kaban da sa para		LIABITA TO F		par is done
	1/3/18 AVE		و المسمر	سأر م
OF		TYPE OF STREE	т <u>СЛ</u>	
	10 1			
경기를 가입니다면 가장 사람들이 없다.	4/03	24 .		339
THE PREMISES BEING	LOT NO /_/	<u>- Norder 77 Albert 144 keust er i Be</u> Politikase Stemaner vilatet vita sat	House No	<u>an da eural de la companya da an anaga</u> An ang ang ang ang ang ang ang ang ang an
WORK TO BE DONE IN	ACCORDANCE WITH ORD	INANCE No. 232	3. DULY PASSED	BY THE CITY COUNT
RULES OF THE DEPAR	TMENT OF PUBLIC SERVIC			
	-4/1/1			
[생생님] [1] 시작(설립 설립하다)	AY. O	mask		
NAME OF CONTRACTO				
and the second s				

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.