

No. 4484

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-6-44

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

Not determined

HOUSE NO. ?

SIZE OF PIPE USED 6

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

5' deep in back of curb. No
known where old 4" passes under

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Garage on rear
of lot used as
Pattern Shop.
No house
on front
of lot.



Old 4" Lateral found. Used 4" x
reducer and new line is 6" L.
is 5' Deep at this point
→ N.

From Reducer to $\frac{1}{8}$ Bend
" $\frac{1}{8}$ Bend to Garage
Total =

SIGNED R. J. Snyder.

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Because of bad trench this line was layed from Walk to ga
old 4" lateral found at walk but too high. Followed 4" lateral until
depth was great enough to connect with 4" x 6" reducer.

N^o 4484

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO.

RECEIVED OF

Mrs Emma Hostetter

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

A. J. Diana

TO TAP

sanitary

SEWER, ON THE

south

OF

Lin May E.

AVE.,
ST.,

TYPE OF STREET

asphalt

THE PREMISES BEING LOT NO.

291

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

A. J. Diana

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.