

Nº 4513

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 11/24/44

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE UP STREAM 86

HOUSE NO. 714

SIZE OF PIPE USED 6" UP DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT 86' 6' deep  
CURB LINE AND DEPTH

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Smart

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

14TH ST. SW

N.



SIGNED John E. Sherrer  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

OK. 11-28-44

Nº 4513

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

# PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/22

RECEIVED OF L. W. Smart

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Chas. Moore

TO TAP Sanitary

SEWER, ON THE East

OF 141 E. 11th St.

AVE.,  
ST.,

TYPE OF STREET dirt

THE PREMISES BEING LOT NO. 4720

HOUSE NO. 714

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L. W. Smart

Note. This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.