

Nº 4523

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4/10/45

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

300'

HOUSE NO. 611

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Smarti

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

29th St. N.W.



SIGNED John E. Shuman
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 4-23-45

REMARKS: Lateral #7 Used

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4523

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/10RECEIVED OF L. W. SmartFEE OF \$ 2FOR WHICH PERMISSION IS GRANTED nick knydenTO TAP sanitarySEWER, ON THE westOF 29th StAVE., TYPE OF STREET hard surfaceTHE PREMISES BEING LOT NO. 0222HOUSE NO. 611

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L. W. Smart

Note. This permit covers work outside of building only. Any work in
 walls of building is subject to Massillon Board of Health Regulations.