

Nº 4525

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4/23/45

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

66'

HOUSE NO. 2649

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

66'

6' deep

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? yes.


WAS ATTACHED TO MAIN yes.

NAME OF CONTRACTOR George Earley.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lincoln Way. N.W.

← N. →



SIGNED John Cherner

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

4-23/45

REMARKS: No 2 Laterals Used

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4525

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/12RECEIVED OF Mrs Helen BeachFEE OF \$ 2⁰⁰FOR WHICH PERMISSION IS GRANTED Her Early & J A. GregoryTO TAP SanitarySEWER, ON THE SouthOF Lin MayhewAVE.,
ST.,TYPE OF STREET pavedTHE PREMISES BEING LOT No. 4378HOUSE No. 2649

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Her Early & J A. Gregory

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.