

Nº 4526

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-18-45

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 716

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

123 ft 6'-6" Deep

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN —

NAME OF CONTRACTOR Smart

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

*Had this spec on
books -*

N. ←



SIGNED

John Chmese

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

4-19-45

REMARKS:

Chmese inspected. Sketch made by engineer from his notes.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 4526

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/16

RECEIVED OF

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE. TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work in
 walls of building is subject to Massillon Board of Health Regulations.