Nº 4569

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-8-45	- IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 5
HOUSE NO. 327	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 58 9 4 CE/1
WAS LATERAL AT CURBI Y = 5	
WAS ATTACHED TO MAIN VES	NAME OF CONTRACTOR Keuhen
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED. Ave. N.E. Token To
SIGNED INSPECTOR FOR CI	FILED AT ENGINEER'S OFFICE I molliseasti on josedna si ambino io gira 10-17-15

Nº 4569

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	elosa senastros delá			10/20120	
	PP		SSILLON, OHIO,		.1
RECEIVED OF		P'0	The same	FEE OF \$_	
TO TAP A		SEWER, ON			1
	i envisida e entre la elektrología (los elektrología elektrología)	AVE	STREET	dit.	
THE PREMISES BEING	LOT NO. / O	-st., 594	, House No	. 327	
					<u>.</u>

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Counc

NAME OF CONTRACTOR TO MULTIPLE

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.