## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR $N_0$ 4601 AND SIGNED WHEN RETURNED DATE INSPECTED 10-18-46 IF SO HOW AND LOCATION FROM 1781 FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT SIZE OF PIPE USED \_\_ CURB LINE AND DEPTH WAS LATERAL AT CURB? Yes WAS ATTACHED TO MAIN \_\_\_\_\_\_\_ NAME OF CONTRACTOR SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. Connecticut. Ave. FILED AT ENGINEER'S OFFICE

## Nº 4601

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		Massillon, Ohio,	ooo
RECEIVED O	- <u>C</u> · (4) 4446	the transmitted of	FEE OF \$
	of grant and a surveying season. It is a regard to the state of the survey of the state of the s	authe	
FOR WHICH PERMI	SSION IS GRANTED	and the second s	AJ
TO TAP	5EW	ER, ON THE	4
of Jarran	eticut UEx. T	YPE OF STREET	4
		5 <b>4</b>	
THE PREMISES BEI	NG LOT No.	, House No.	for the same

NAME OF CONTRACTOR Q ULana

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.