

Thomas Bendure

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
Nº 4614 AND SIGNED WHEN RETURNED

DATE INSPECTED 7-8-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

78'

HOUSE NO. 1608

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

78'

8' deep

SIZE OF PIPE USED 6

WAS LATERAL AT CURB? No


WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR

Bluestone

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

1324 S.T. S. E.



M.H. 78'

8' deep

80

10

SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

OK 7-15-46

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4614

PERMIT TO TAP SEWER

MASSILLON, OHIO, 2/14RECEIVED OF L. BluestoneFEE OF \$ 2FOR WHICH PERMISSION IS GRANTED L. BluestoneTO TAP SanitarySEWER, ON THE EastOF 13th StAVE.,
ST.,TYPE OF STREET dirtTHE PREMISES BEING LOT NO. OL 298HOUSE NO. 1608

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L. Bluestone

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.