

Nº 4617

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-10-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

97'

HOUSE NO. 1613

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

97'

8' deep

SIZE OF PIPE USED 6

WAS LATERAL AT CURB? No


WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR

Blue Stone

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED

13th St. S.E.



SIGNED

John E. Humer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

OK 7-15-46

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 4617

PERMIT TO TAP SEWER

MASSILLON, OHIO, 2/14RECEIVED OF M. BluestoneFEE OF \$ 2FOR WHICH PERMISSION IS GRANTED M. BluestoneTO TAP SanitarySEWER, ON THE WestOF 13th St. E.AVE., TYPE OF STREET dirtTHE PREMISES BEING LOT NO. 07 298HOUSE NO. 1613

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR M. Bluestone

Note. This permit covers work outside of building only. Any work
 walls of building is subject to Massillon Board of Health Regulations.