

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-9-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 77 John Had 87°

HOUSE NO. 1331

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 77 — 7' deep

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes


NAME OF CONTRACTOR Bluestone

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

3TH ST. S.E.



M.H. 87



SIGNED John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE OK 3-22-46 Doc

REMARKS: Ehmer 87° From M.H. South. Finals show 77° and also scales 77° Doc

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4624

PERMIT TO TAP SEWER

MASSILLON, OHIO, 2/14

RECEIVED OF

M. Bluestone

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

M. Bluestone

TO TAP

Sanitary

SEWER, ON THE

West

OF

3rd St. E

AVE., TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

5398

HOUSE NO.

1331

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Bluestone

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.